

### Abstract

A method for the agglomeration of alumina particles, the method comprising the steps of:  
adding a quantity of pseudo-boehmite to the alumina particles; and  
spray drying the mixture so formed to produce agglomerated granules.

4455860